# LSG not recognizing easYgen-3000XT in firmware 2.10, 2.10-1 & 2.10.2

Justin Schneider - 2026-07-27 - LSG

In easYgen-3000XT release  2.10, 2.10-1, 2.10-2 the LSG load share gateway was not recognized.

Please upgrade your easYgen-3000XT controls to latest corrected firmware you can download here:

https://wss.woodward.com/manuals/Support/Forms/AllItems.aspx