



[Knowledgebase](#) > [easYgen-3000XT](#) > [easYgen-2000 application limitation compared to easYgen-3000XT Line](#)

## **easYgen-2000 application limitation compared to easYgen-3000XT Line**

Clemens - 2024-09-27 - [easYgen-3000XT](#)

Multiple gensets controlled by easYgen-2000 line controls **cannot** serve GCBs and a MCB because

easYgen-2000 controls not have a bus bar voltage measurement between GCB (Generator Circuit Breaker) and MCB (Mains Circuit Breaker)

