



Knowledgebase > Turbine Articles > RE: Governor Panel HMI 8236-1001

RE: Governor Panel HMI 8236-1001

Peter Terrio - 2019-07-29 - Comments (0) - Turbine Articles

If a customer requests a replacement for a 5009 touch screen HMI. Please contact Tim Harwick to find the best solution. Currently Woodward does not offer a drop in replacement and a replacement will be provided on a case by case basis.