



ナレッジベース > Turbine Articles > 505XT resets IP address on power cycle

505XT resets IP address on power cycle

David Lynch - 2017-10-19 - Comments (0) - Turbine Articles

This issue was addressed in the Rev. A of the 505XT GAP Application.

I would recommend updating to the latest revision of the 505XT GAP and GUI.

The software can be downloaded by going to: <http://www.woodward.com/software.aspx>

Search: "505XT"

Procedures for updating the applications are in the 'More Info' link.

タグ
505XT
IP