



[Knowledgebase](#) > [Power Management](#) > [DSL](#)C > [Handheld replacement for DSLC first generation](#)

Handheld replacement for DSLC first generation

Justin Schneider - 2026-07-27 - [DSL](#)C

DSL

C and MSLC were configured with the Handheld Programmer 9907-205. However, this programmer has been made obsolete by Woodward in September 2022, as stated in the Product Support Statement provided in this [link](#).

A suitable replacement for the programmer can be obtained from Termiflex Warner company at www.termiflex.com.

Woodward excludes any technical liability for this aftermarket solution, as it has not been tested.

