



[Knowledgebase](#) > [Power Management](#) > [easYview](#) > [HMI Deltas of RP-3000XT versus easYview HMI panel](#)

HMI Deltas of RP-3000XT versus easYview HMI panel

Justin Schneider - 2026-07-27 - [easYview](#)

RP-3000XT in field can be replaced by easYview panels configured for VNC HMI mode.

Keep in mind that the easYview navigation bar on the left side cannot be removed

