



Knowledgebase > Turbine Articles > How to resolve problems connecting GAP and Control Assistant to the OPC SOS Server?

How to resolve problems connecting GAP and Control Assistant to the OPC SOS Server?

Simon - 2024-04-26 - Comments (0) - Turbine Articles

Please check out the OPC & DCOM Troubleshooting: Quick Start Guide made by the OPC Training Institute:

<https://www.opcti.com/opc-dcom-five-tips.aspx>

Please check whether the SOS is running at the same elevation level as GAP and C.A.?